

# Quotations



## **Boat Work Service Ltd.,part**

**(Yacht Management Painting & Woodworks)**

20/58 Moo 2 Thepsasattri R. A Muang Phuket Thailand 83000  
Email: info@Boatworkservice.com Boatworkservice@hotmail.com

**Tell: +66 (0)81 788 8951 +66 (0)86 268 3714**

[www.Boatworkservice.com](http://www.Boatworkservice.com)

**Company Registration No.3-0335-5425-0**

- |               |               |
|---------------|---------------|
| * Woodworking | * Painting    |
| * Furniture   | * Antifouling |
| * Teak Deck   | * Fiberglass  |
| * Vanishing   | * Re-osmosis  |

.....  
\* Office in Phuket Boat lagoon marina **Tell: +66 (0)81 788 8951**

\* Office in Krabi Boat lagoon marina **Tell: +66 (0)86 268 3714**

Attention: The... Owner... Captain... Manager of ...C/Y Migration... ) Yacht

From: Mr. Gig Repair.

Ret: Yacht work

Date: 22/02/2013

.....  
We are please to give you the quotation for all work by discussion as following

## **Quotations**

### **Top sides (Hull)**

#### **1. Strip fiberglass from top sides**

-Cost of tools and labor = 60,000- Baht

**Total =60,000-Baht.**

.....  
**2. Replace fiberglass top sides.(put epoxy filler) Sand and fair to be smooth**

-Cost of materials = 210,000- Baht

-Cost of labor = 90,000-Baht

**Total =300,000-Baht.**

.....  
**3. Prep and paint top side Awlcraft Red color 85m<sup>2</sup>**

-Cost of materials = 280,000- Baht

-Cost of labor = 187,000-Baht

**Total =467,000-Baht.**

.....  
Cost all of topside works =827,000 Baht.

**Deck and cockpit**

**1. Sanding paint from deck and cockpit**

-Cost of tools and labor = 12,000- Baht  
**Total =12,000-Baht.**

**2. Repaint deck and cockpit areas. Both smooth and non-skid with Awl Craft 110m<sup>2</sup>**

-Cost of materials = 363,500- Baht  
-Cost of labor = 242,000-Baht  
**Total =605,500-Baht.**

Cost all of deck and cockpit works =617,500 Baht.

**Bottom**

**1. Strip off old antifouling paint (The owners already has antifouling paint)**

-Cost of materials = 22,500- Baht  
-Cost of labor = 16,000-Baht  
**Total =38,500-Baht.**

Cost all of bottom works =38,500 Baht.

**Interior**

**1. Re-varnish interior 4 coats of gloss and 2 coats of satin top coat**

-Cost of materials = 82,500- Baht  
-Cost of labor = 55,000-Baht  
**Total =137,500-Baht.**

Cost all of varnish works =137,500 Baht.

**-The cost all works to do on your boat = 1,620,500 Baht.**

- The time need to do 3 months**
- Guaranteed 2 years after work done**

.....  
**(Mr.Gig. Contractor)**

Remake: If have something change offer from agreements have to change the Cost also with following the price of materials

**Payment:** 50 %Deposit-before work for buy materials  
30% after (the first time about 50% of work)  
20% when finish already.

**ID:** 18401 00008 217 **The Contractor Mr.Wararob (Gig) Punpuech**

.....  
**Swift Code.**

The Siam Commercial Bank PLC.      Sub Branch:      **Phuket Boat lagoon Branch.**  
14/1 M.2 Thepkasattri Rd.Koh kaew,Mueang,Phuket 83000 Thailand(66-76)204104,204105  
Fax: (66-76) 204106 [www.scb.co.th](http://www.scb.co.th)      Mail,886@SCB.CO.TH  
Account No. **886-208904-4**      Name: **Boat Work Service Lid.,part**  
Swift Code: SICOTHBK Telex      No.: 20455 SIAMFX TH

.....

.....

.....

The Contractor

.....

The owner,caption,manager

1. Date.....Pay deposit.....THB. Receipt by.....

Pay by.....

.....  
Mr.Gig.manager  
Boat work Service Ltd.,Part  
[www.Boatworkservice.com](http://www.Boatworkservice.com)  
086 268 3714